

2016 – Notice to Shipping N° 5 MAISONNEUVE REGION MONTREAL / LAKE ONTARIO SECTION

## Speed Reduction at the Port of Valleyfield

Following a broken mooring line incident, mariners will be asked to transit at the slowest safe speed possible when passing by a vessel secured at the eastern part of the Port of Valleyfield, especially when meeting another vessel.

In addition, vessels mooring at the eastern part of the port of Valleyfield are to do so safely in order to avoid broken mooring lines caused by marine traffic and meets occurring in this area.

Thank you for your collaboration.

Maisonneuve Region

March 10, 2016

The St. Lawrence Seaway Management Corporation Corporation de Gestion de la Voie Maritime du Saint-Laurent