


## 2016 – Notice to Shipping #19 MAISONNEUVE REGION MONTRÉAL / LAKE ONTARIO SECTION

## LOW WATER LEVELS ON LAKE ST. LOUIS

Mariners are advised that due to low water levels on Lake St. Louis, the speed limit between buoys A30 to A40 is **reduced to 10 knots for all vessels, upbound and downbound**. Vessel speeds will be monitored closely.

In addition, we are asking mariners to avoid sailing over and SOUTH of the following positions:

Two positions at 450 and 560 meters EAST of buoy A33 and at 80 meters NORTH of the SOUTH canal line.



Also avoid sailing over and NORTH of the following positions: At 300 meters EAST of buoy A35 and 50 meters SOUTH of the NORTH canal line • 45 degrees 21.96 minutes NORTH 73 degrees 49.97 minutes WEST

> The St. Lawrence Seaway Management Corporation Corporation de Gestion de la Voie Maritime du Saint-Laurent

Région Maisonneuve 151, rue de l'Écluse St-Lambert, Québec J4R 2V6 Tél : (450) 672-4115 Fax : (450) 672-8493 
 Niagara Region


 508 Glendale Avenue

 P.O. Box 370


 St-Catharines, Ontario

 L2R 6V8

 Tél : (905) 641-1932



At 130 meters WEST of buoy A38 and 40 meters SOUTH of the NORTH canal line. • 45 degrees 21.56 minutes NORTH 73 degrees 50.55 minutes WEST



We will monitor the water levels closely and advise you of any changes as conditions improve.

Maisonneuve Region October 3, 2016

> The St. Lawrence Seaway Management Corporation Corporation de Gestion de la Voie Maritime du Saint-Laurent

**Région Maisonneuv**e 151, rue de l'Écluse St-Lambert, Québec J4R 2V6 Tél : (450) 672-4115 Fax : (450) 672-8493 Niagara Region 508 Glendale Avenue P.O. Box 370 St-Catharines, Ontario L2R 6V8 Tél : (905) 641-1932 Fax : (905) 641-5721