

## 2007 - NOTICE TO SHIPPING #23

MAISONNEUVE REGION MONTREAL/LAKE ONTARIO SECTION

## LOW WATER LEVELS ABOVE COTE SAINTE CATHERINE LOCK - AMENDED

Mariners are advised that due to low water supplies and consequently the low and declining river outflows, low water levels exist in the area immediately above Cote Ste Catherine Lock to the western end of Cote Ste Catherine wharf.

Given the approximately 15 cm normal variation of in the water levels in this vicinity, vessels loaded to a draft of 79.2 dm or greater are to transit this area at the slowest safe speed. Moreover, there will be no meeting allowed in this area for these vessels. The filling of Cote Sainte Catherine lock will be slower when a vessel is approaching or is in this concerned area.

Conditions will continue to be monitored closely and mariners will be advised accordingly.

Maisonneuve Region November 16, 2007

> The St. Lawrence Seaway Management Corporation Corporation de Gestion de la Voie Maritime du Saint-Laurent