

The Great Lakes - St. Lawrence Seaway System Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2012 - NOTICE TO SHIPPING #21

MAISONNEUVE REGION MONTREAL/LAKE ONTARION SECTION

WATER LEVELS ON LAKE ST-LOUIS (Correction to Notice to Shipping #9)

The water levels on Lake St-Louis being close to Seaway alert levels, we are asking mariners to avoid sailing over and SOUTH of the following positions:

Two positions at 450 and 560 meters EAST of buoy A33 and at 80 meters NORTH of the SOUTH canal line.

- 45 degrees 22.34 minutes NORTH 73 degrees 49.38 minutes WEST
- 45 degrees 22.31 minutes NORTH 73 degrees 49.43 minutes WEST

Also avoid sailing over and NORTH of the following positions:

At 300 meters EAST of buoy A35 and 50 meters SOUTH of the NORTH canal line

45 degrees 21.96 minutes NORTH 73 degrees 49.97 minutes WEST

At 130 meters WEST of buoy A38 and 40 meters SOUTH of the NORTH canal line.

45 degrees 21.56 minutes NORTH 73 degrees 50.55 minutes WEST

We will advise you of any further changes.

Maisonneuve Region December 10, 2012

The St. Lawrence Seaway Management Corporation Corporation de Gestion de la Voie Maritime du Saint-Laurent

Fax: (450) 672-8493

Fax: (905) 641-1932