

The Great Lakes - St. Lawrence Seaway System Le réseau Grands Lacs - Voie maritime du Saint-Laurent

SEAWAY NOTICE NO. 5 - 2018

Notification Requirement for Use of Lines at HFM Locks (Cancelled 2018/06/25)

If a need is identified to use lines at locks where HFM is installed, for reasons such as equipment malfunction (e.g. bow thruster, engine), HFM equipment out of service, HFM incompatibility, a need for tie-up service, ice covered hulls or other weather conditions, an **advance notice of at least 60 minutes** identifying the need shall be provided, when possible.

- If the need is identified by Seaway personnel, traffic control will advise the vessel.
- If the need is identified by the vessel, then the vessel is to advise the traffic control center.

March 19, 2018

Cornwall, Ontario K6J 3P7 Tel: 613-932-5170 Fax: 613-932-5204 P.O. Box 520 180 Andrews Street Massena, New York 13662-0520

Tel: 315-764-3200 Fax: 315-764-3250