

The Great Lakes - St. Lawrence Seaway System Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2007 - NOTICE TO SHIPPING #5

MAISONNEUVE REGION MONTREAL/LAKE ONTARIO SECTION

SECURITY AWARENESS WHILE ENTERING / DEPARTING SEAWAY LOCKS

Mariners are requested to be attentive to the non tie-up side of the lock, particularly when entering/exiting locks and during mooring operations as lock employees' visibility of the non tie-up side is periodically obstructed by the vessel.

If at any time suspicious or dangerous activity is observed on the non tie-up side of the lock, mariners are requested to immediately advise lock personnel and/or the operations centre via VHF and, upon notification, the SLSMC will respond and/or contact appropriate authorities.

Maisonneuve Region May 29, 2007

The St. Lawrence Seaway Management Corporation Corporation de Gestion de la Voie Maritime du Saint-Laurent

Tel: (905) 641-1932 Fax: (905) 641-5721