

2010 - NOTICE TO SHIPPING # 2

MAISONNEUVE REGION MONTREAL / LAKE ONTARIO SECTION

Vessel self-spotting systems at locks 1, 2, 3 & 4

During the 2009 navigation season, The St. Lawrence Seaway Management Corporation tested and evaluated a vessel self-spotting system at locks 1, 2, 3, and 4 with good results and feedback. Mariners are advised that testing will continue at these locations during the 2010 navigation season.

This equipment uses eye safe laser ranging technology, located at both ends of the lock, to recognize the foremost portion of the vessel's hull and estimate its position in the lock. The vessel's position will be updated dynamically and displayed on both LED panels, located on the tie up side of the lock, as the vessel progresses to its final mooring position.

The lock leader will inform the vessel if it is qualified and if the Self-Spotting system is operational, during the initial communication, once the ship is at the limit of approach. The spotting instructions from the lock personnel are to be respected.

Master/Pilots are asked to provide any comments/concerns with respect to the vessel selfspotting system directly to the lock crew who will record them on the appropriate test form.

Maisonneuve Region March 19, 2010

Région Maisonneuve 151, rue de l'Écluse St-Lambert, Québec J4R 2V6 Tél : (450) 672-4115 Fax : (450) 672-8493 Niagara Region 508 Glendale Avenue P.O. Box 370 St-Catharines, Ontario L2R 6V8 Tél : (905) 641-1932 Fax : (905) 641-5721