

The Great Lakes - St. Lawrence Seaway System Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2011 - Notice to Shipping # 6

MAISONNEUVE REGION MONTRÉAL / LAKE ONTARIO SECTION

High Water Levels

Mariners are advised that high water levels exist in the Morrisburg area. For this reason, the speed limits indicated in Column IV of the Seaway Handbook are in effect immediately between Eisenhower and Iroquois Lock. The Traffic Control personnel will monitor the water levels. Mariners are also advised to watch their wakes as higher water level are also present throughout sector 3 (Bradford Island to Cross Over Island). Mariners will be advised once the levels have receded.

Maisonneuve Region June 1, 2011

Tél: (905) 641-1932 Fax: (905) 641-5721