

The Great Lakes - St. Lawrence Seaway System Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2012 - NOTICE TO SHIPPING #10

MAISONNEUVE REGION MONTREAL/LAKE ONTARION SECTION

Low Water Levels above Cote St. Catherine Lock

Further to Seaway Notice no.10, and Maisonneuve Region Notices to Shipping #6, #8 and #9 of 2012, Mariners are advised that due to low water supplies and consequently the low and declining river outflows, low water levels exist in the area immediately above Cote St. Catherine Lock to the western end of Cote St. Catherine wharf. Given the approximately 15 cm normal variation in the water levels in this vicinity, vessels loaded to a draft of 78 dm or greater are to transit this area at the slowest safe speed. Conditions will continue to be monitored closely and mariners will be advised accordingly.

Maisonneuve Region June 19, 2012

> The St. Lawrence Seaway Management Corporation Corporation de Gestion de la Voie Maritime du Saint-Laurent

Fax: (905) 641-5721