

## The Great Lakes - St. Lawrence Seaway System Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2013 – NOTICE TO SHIPPING #39

## MAISONNEUVE REGION MONTREAL/LAKE ONTARION SECTION

## **RESTRICTIONS - LAKE ST. LOUIS WATER LEVELS**

Mariners are advised that due to declining water levels on Lake St. Louis, the speed limit between buoys A30 to A40 is reduced to 10 knots for both upbound and downbound vessels. Vessel speeds will be monitored closely.

Mariners are also asked to avoid sailing over and SOUTH of the following positions:

Two positions at 450 and 560 meters EAST of buoy A33 and at 80 meters NORTH of the SOUTH canal line.

- 45 degrees 22.34 minutes NORTH 73 degrees 49.38 minutes WEST
- 45 degrees 22.31 minutes NORTH 73 degrees 49.43 minutes WEST

Also avoid sailing over and NORTH of the following positions:

At 300 meters EAST of buoy A35 and 50 meters SOUTH of the NORTH canal line

• 45 degrees 21.96 minutes NORTH 73 degrees 49.97 minutes WEST

At 130 meters WEST of buoy A38 and 40 meters SOUTH of the NORTH canal line.

45 degrees 21.56 minutes NORTH 73 degrees 50.55 minutes WEST

We will continue to monitor the situation and will keep mariners advised accordingly.

Maisonneuve Region December 23, 2013

The St. Lawrence Seaway Management Corporation Corporation de Gestion de la Voie Maritime du Saint-Laurent

Fax: (905) 641-1932