



The Great Lakes - St. Lawrence Seaway System
Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2015 - Notice to Shipping N° 9

MAISONNEUVE REGION

MONTREAL / LAKE ONTARIO SECTION

Security at approach / tie-up walls

This notice to shipping replaces and voids notice to shipping N° 5 of 2015.

Mariners are reminded that the Seaway approach/tie-up walls are considered controlled areas under the Marine Transportation Security Regulations.

If a ship conducts an interface at a Seaway approach/tie-up wall, the Seaway operations centre must be advised ahead of time.

Access control of persons wanting to go to the ship at the approach/tie-up walls or to disembark from the ship at the approach/tie-up walls must be performed at the main access gate before heading to the approach walls or leaving the lock.

Surveillance at Seaway approach/tie-up walls is performed with video cameras.

The ship must advise the operations centre if a security incident or a threat occurs around the ship. Measures will be put in place in response to the situation.

Maisonneuve Region
May 26, 2015

The St. Lawrence Seaway Management Corporation
Corporation de Gestion de la Voie Maritime du Saint-Laurent

Région Maisonneuve
151, rue de l'Écluse
St-Lambert, Québec
J4R 2V6

Tél : (450) 672-4115 Fax : (450) 672-8493

Niagara Region
508 Glendale Avenue
P.O. Box 370
St-Catharines, Ontario
L2R 6V8

Tél : (905) 641-1932 Fax : (905) 641-5721