

## 2019 – Notice to Shipping #36 MAISONNEUVE REGION MONTRÉAL / LAKE ONTARIO SECTION

## Vessel Speed Restriction Eisenhower Lock to Tibbetts Point

Mariners are advised that due to a decrease in water levels the speed limits outlined in **Column III** of *Schedule II – Table of Speeds in the Seaway Handbook Practices & Procedures* will now be applied from Eisenhower Lock to Tibbetts Point.

Mariners are reminded to watch their wake, particularly when navigating close to shore.

Please note that the speed restrictions outlined in Montreal – Lake Ontario Notices to Shipping No. 35 and No. 23 regarding the high spots at Galop Island and in U.S. Sector IV remain in effect.

We will continue to closely monitor the water levels closely and advise you of any changes.

Maisonneuve Region October 1, 2019

> The St. Lawrence Seaway Management Corporation Corporation de Gestion de la Voie Maritime du Saint-Laurent