

## 2013 - NOTICE TO SHIPPING #7

NIAGARA REGION WELLAND CANAL

## Lock 2 Upper Tie Up Wall

Inspection and assessment of the Lock 2 Upper West Tie Up Wall has identified a section of the wall that will require rehabilitation. Mariners are therefore advised that the Lock 2 Upper West Tie Up Wall between bollards 17 - 23 will be restricted for impact loading. Vessels should land outside this barricaded and identified area.

Sliding the wall, along with landing personnel for tie up is still permitted. Fencing and owl lights have been erected on the wall marking the area in question. Vehicular traffic is restricted to the access road and should not enter the above mentioned area. These restrictions will remain in place for the entire 2013 navigation season.

Glenn Rutherford Process Support Coordinator - Canal Services St.Catharines, Ontario

March 21, 2013